Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	523	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with surface with shape	US-PGPUB; USPAT; EPO; DERWENT	OR .	ON	2006/10/04 07:13
L2	15	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with surface with shape with workpiece	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:47
L3	2	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with surface with shape with workpiece and ((trace) or (tracing) or (traced))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:21
L4	907	702/127	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:21
L5	295	702/167	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:21
L6	9	1 and 5	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:29
L7	189	702/168	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:29
L8	289	702/170	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:30
L9	1504	702/150	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:30
L10	606	702/155	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:30
L11	125	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with surface and shape and workpiece	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:16

			 	·		
L12	3	5 and 11	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:49
L13	385	702/158	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:48
L14	3	12 and ((trace) or (tracing) or (traced) or (change) or (changed) or (changing))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:52
L15	0	12 and ((trace) or (tracing) or (traced) or (change) or (changed) or (changing)) and ((robot) or (robotic))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:53
L16	23	11 and ((trace) or (tracing) or (traced) or (change) or (changed) or (changing)) and ((robot) or (robotic))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:57
L17	5	11 and ((trace) or (tracing) or (traced) or (change) or (changed) or (changing)) and ((robot) or (robotic)).CLM.	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:53
L18	16	11 and ((trace) or (tracing) or (traced) or (change) or (changed) or (changing)) and ((robot) or (robotic)) and predetermined and distance	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 07:57
L19	8	11 and ((trace) or (tracing) or (traced) or (change) or (changed) or (changing)) and ((robot) or (robotic)) and (predetermined with distance)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:01
L20	447	700/159	US-PGPUB; USPAT; EPO; DERWENT	OR	OFF	2006/10/04 08:00
L21	337	700/160	US-PGPUB; USPAT; EPO; DERWENT	OR	OFF	2006/10/04 08:00
L22	93	700/161	US-PGPUB; USPAT; EPO; DERWENT	OR	OFF	2006/10/04 08:00

			•			•
L23	1	11 and ((trace) or (tracing) or (traced)) and ((robot) or (robotic)) and (predetermined with distance)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:02
L24	2	1 and ((trace) or (tracing) or (traced)) and ((robot) or (robotic)) and (predetermined with distance)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:05
L25	14	((trace) or (tracing) or (traced)) with surface with ((shape) or (shaped) or (shaping)) and ((robot) or (robotic)) and (predetermined with distance)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:05
L26	39	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with (surface with shape) and workpiece	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:33
L27	8	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with (surface with shape) and workpiece and (predetermined with distance)	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:18
L28	3	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with (surface with shape) and workpiece and ((record) or (recorder)) and ((trace) or (tracing) or (traced))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	. 2006/10/04 08:36
L29	1	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with (surface with shape) and workpiece and (predetermined adj distance) and ((trace) or (tracing) or (traced))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:37
L30	2	measuring with ((three adj dimensional) or (3D) or (three-dimensional)) with (surface with shape) and workpiece and (predetermined adj distance) and ((record) or (recorder) or (recording))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:42
L31	2	"6642470".pn.	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:40
L32	1	31 and ((trace) or (tracing) or (traced) or (change) or (changing) or (changed) or (exchange) or (exchanging))	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:39

L33	1043	33/503	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:42
L34	275	33/554	US-PGPUB; USPAT; EPO; DERWENT	OR	ON	2006/10/04 08:42

10/4/06 8:42:24 AM C:\Documents and Settings\BBui\My Documents\EAST\Workspaces\10729651.wsp